


# **Monthly SLA Report | January**

# Woodmead\_Khyber\_Park



#### Cameras

All cameras covered by the applicable contract

### All camera downtime

The total summation of all downtime for all cameras. For clarity, if a pole had four cameras (overview or LPR) down simultaneously for an hour the total downtime would be calculated as 4 cameras x 1 hour = 4 hours downtime.

#### Average per camera downtime

The average downtime or time for a camera to come online over the entire base of cameras over the reporting period.

#### Downtime percentage

The downtime as a percentage over the entire base of cameras over the reporting period. SLA allowable downtime is 3.0%.

## **Availability percentage**

The availability or normal expected working condition of the entire fleet of cameras over the reporting period. Target availability percentage is 97.0%

\*Total service availability (SLA availability) does not include downtime caused by maintenance of the system; service unavailability caused by events outside our, or our personnel's reasonable control such as loss of electricity, adverse weather conditions, any fiber network outage or vandalism, and excludes the failure or unavailability of your facilities or systems such as internet connectivity, any other service or third-party used by you to use, connect to, or access the service.

| Camera Name                              | MTTR<br>(hours) | Downtime<br>(hours) | Uptime<br>(hours) | Availability<br>% | SLA Availability<br>% |
|--|-----------------|---------------------|-------------------|-------------------|-----------------------|
| Wdmd_Hillman Str and Plymouth Str_15.1_O | 00.00           | 00.00               | 744.00            | 100.00            | 100.00                |
| Wdmd_Hillman Str and Plymouth Str_15.2_O | 00.00           | 00.00               | 744.00            | 100.00            | 100.00                |
| WDMD_Lincoln St_17.2_O                   | 00.00           | 00.00               | 744.00            | 100.00            | 100.00                |
| WDMD_Lincoln St_17.3_O                   | 00.00           | 00.00               | 744.00            | 100.00            | 100.00                |
| WDMD_Lincoln St_17.4_M                   | 00.00           | 00.00               | 744.00            | 100.00            | 100.00                |
| Wdmd_Plymouth Str and Lincoln Str_14.1_O | 25.83           | 25.83               | 718.17            | 96.53             | 100.00                |
| Wdmd_Plymouth Str and Lincoln Str_14.2_O | 25.83           | 25.83               | 718.17            | 96.53             | 100.00                |
| Wdmd_Plymouth Str and Lincoln Str_14.3_O | 25.83           | 25.83               | 718.17            | 96.53             | 100.00                |
| Wdmd_Riley Str (Boomgate)_16.2_O         | 22.46           | 89.83               | 654.17            | 87.93             | 100.00                |
| Wdmd_Riley Str (Boomgate)_16.3_O         | 22.46           | 89.83               | 654.17            | 87.93             | 100.00                |
| Wdmd_Riley Str (Boomgate)_16.5_M         | 22.46           | 89.83               | 654.17            | 87.93             | 100.00                |